

For the 2nd half of 2018

PSC Trend

Nov. 20, 2018 K.H. Hwang / Survey Team



Contents

- I. Statistics for the 2nd half
- II. PSC Issue



I) Statistics for the 2nd half



Summary of the 2nd half of 2018

1. Period: 2018. 07. 01 ~ 2018. 11. 20

2. Detention: Total 20 ships (owner-related)

* The 1ST half of 2018: Total 40 ships


3. Summary

- Compared with the first half of the year, the number of detained ships was sharply decreased in half. (40 Ships -> 20 Ships until now)
 - -> It is judged that PSC Seminar started in June this year by overseas branch office was effective.
- 2 The detention of foreign managing company is relatively high compared to the ratio of the registered ship in KR.
- 3 Fire safety & ISM were the cause of the highest detention.














July to November _ by PSC country





*1 Others: France, Spain, Indonesia, New Zealand, USA, Sri Lanka, Korea






July to November _ by managing company







July to November _ by Ship Type




Detained ship No. / Portion

I. Statistics for the 2nd half



July to November _ by Detention Items





July to November _ by Detention Items in detail (1)

Category	Details for Detention item
Fire Safety	 Defective on Self-Closing Fire Door Defective on Fire Damper / Funnel Damper (not fully closed, holed) Oil leaking from machinery in engine room (Important in USA) Oil soaked lagging and oil rags in engine room (Important in USA)
ISM	 No familiarity on DSC Call of MF/HF No familiarity on Fuel Oil Change for SECA area No familiarity on Voyage Plan, Chart and ECDIS ISM failure due to many deficiencies
Life Saving	 Defective on Life Boat Engine Starting (battery was discharged) Defective on Rescue Boat Steering (malfunction) Defective on Rescue Boat Launch Davit (Power Failure)
Safety of Navigation	 Defective on Gyro Compass (out of order) No charts on board
Marine Pollution	 O.W.S; Hole/Corrosion in Suction Pipe Sewage Treatment Plant; out of order Fuel Oil Change Procedure; not followed the SECA Requirement



July to November _ by Detention Items in detail (2)

Category	Details for Detention item
Emergency Items	 Defective on Emergency Fire Pump Defective on Emergency Generator (Battery was discharged)
Cert / Document	 No Safe Manning Cert on board No GMDSS General Operator Cert for Master on board
Tightness Condition	1) Cargo hatch cover; not weather tight (corroded / holed / light came in hold)
ISPS	1) No access control for visitors
Machinery	1) Defective on Generator Engines (No.1 & No.3)
Radio Equipment	1) No reserve source of energy for MF/HF & INMARSAT-C




PSC Issue

Ⅱ PSC Issue



(Oily Water Separator) Unapproved pipe line







Deficiency

Unapproved pipe line from sludge pump was connected to overboard line of O.W.S.

[ship transferred from other class]



Action Taker

It was removed from the overboard line.



Preventive Measure

Pipe line shall be carefully checked during class survey by KR and patrol by Engineers on board.

Ⅱ PSC Issue




(Emergency Fire Pump) No Control means for sea inlet valve

Requirement

[SOLAS Ch.II-2/Reg.10.2.1.4.1] / Ships constructed on or after July 01, 2002

The emergency fire pump, its seawater inlet, and suction and delivery pipes and isolating valves shall be located outside the machinery space. If this arrangement cannot be made, the sea-chest may be fitted in the machinery space if the valve is remotely controlled from a position in the same compartment as the emergency pump



Deficiency

No remote control means was provided in S.G.Room. (It was fitted in F.C.Station, not in S.G.Room.)

[ship transferred from other class]



Action Taker

It plans to be fitted in the same compartment(S.G.Room) with the emergency fire pump.




Preventive Measure

It shall be carefully checked during class survey by KR and patrol by Engineers on board.

Ⅱ. PSC Issue



(Cargo Hatch Cover) Tightness



[Holed and Corroded]

Deficiency

After closing h/cover, PSCO found h/cover was not weather tight due to corrosion and holes.



After the temporary repair, the ship went to the next port for the permanent repair.



Preventive Measure

After closing it, check whether light is transmitted or any corrosion is found.

II. PSC Issue






(Radio Communication) Missing radio communication

Requirement

[SOLAS Ch.IV/Reg.7.2] / Applicable to all Passenger Ships / Retroactive Requirement

<u>Every passenger ship shall be provided with means for two-way on-scene radio communications</u> for search and rescue purposes <u>using the aeronautical frequencies 121.5MHz and 123.1MHz</u> from the position from which the ship is normally navigated.



[Sample_Portable Type]

Deficiency

Two-way on-scene radio communication means was not provided on board.



Action Taken

Newly provided due to it's loss



Preventive Measure

For passenger ship, check whether it is provided on board.









KR Survey Team psc@krs.co.kr