




**Subject: Flag instruction for COSMO faulty fire doors  
(Marshall Islands)**

▪ The Marshall Islands Administration recently issued Marine Safety Advisory No. 12-18, attached herewith, in order to provide instructions for shipowners/operators regarding the faulty fire doors manufactured by COSMO CO.,Ltd and the main contents are as follows.

A. Criteria

- (1) A-60, A-0, and B-15 class fire doors;
- (2) certified to MED Modules B and D, type-approved by DNV-GL;
- (3) produced between November 2013 and July 2017.



B. Action to be taken by shipowners/operators

- (1) confirm the condition of fire doors and carry out proper repair work, if applicable.
- (2) If any such fire doors are found to be affected, contact the Administrator at [technical@register-iri.com](mailto:technical@register-iri.com), as well as this Society.

For details, please find attachment.

Attachment : MSA No.12-18. END.

Distributions : Ship owners & Operators, KR surveyors, Other stakeholders

**Disclaimer** : Although all possible efforts have been made to ensure correctness and completeness of the contents contained in this information service, the Korean Register of Shipping is not responsible for any errors or omissions made herein, nor held liable for any actions taken by any party as a result of information retrieved from this information service.