海事處

船舶事務科

香港 中環 統一碼頭道 38 號 海港政府大樓 24 樓

電話號碼: (852) 2852 4510 傳真號碼: (852) 2545 0556

Web Site: http://www.mardep.gov.hk 電郵地址 E-mail: SS CSS@mardep.gov.hk

貴署檔案 Your Ref.: ---

本處檔案 Our Ref.: SD/S 800/1



MARINE DEPARTMENT

Shipping Division

24/F., Harbour Building, 38 Pier Road, Central, Hong Kong

Tel No.: (852) 2852 4510 Fax No.: (852) 2545 0556

15 June 2018

To: Shipowners / Ship Managers and Classification Societies

Dear Sir/Madam.

Port State Control Detention due to MARPOL Violation

Early this year, about 6 m³ of bilge water was discharged overboard from a Hong Kong registered ship without passing through the oily water separator. In the Oil Record Book, false entry was made and stated that the bilge water was discharged overboard through the oily water separator.

Four weeks later, during a PSC inspection the PSC officer found that there was no record in the data-logger of the oily water separator for the above-mentioned bilge water discharge. Later the Chief Engineer and Fourth Engineer admitted that the 6 m³ of bilge water was discharged overboard without passing through the oily water separator and the ship was then PSC detained.

With respect to the above-mentioned MARPOL violation, we would like to draw your attention that under the requirements of the Merchant Shipping (Prevention of Oil Pollution) Regulations, Cap.413A, Laws of Hong Kong SAR, any seafarer commits such kind of offence, if convicted, will be subject to a fine of HK\$500,000.

In order to avoid such kind of intentional MARPOL violation, all ship managers, ship masters and engineers are urged to review the effectiveness of the shipboard safety management system and ensure accurate entry of Oil Record Book.

Should you have any queries, please feel free to contact the Cargo Ships Safety Section as follows:

Telephone number:

(852) 2852 4510

Fax number:

(852) 2545 0556

E-mail address:

ss css@mardep.gov.hk

Yours faithfully,

(C. L. FONG)

Senior Surveyor/Cargo Ships Safety Section for Director of Marine