

BRIEFING STATUS

Flash

☐ Final.

No. IMO-0009-2019

Briefings of IMO Meeting are sequentially released by 2 steps as Flash - Final.

Subject: Newsflash of MSC 101

The Maritime Safety Committee (hereinafter referred as 'MSC'), its 101st session was held at IMO Headquarter from 5th to 14th June, 2019. With this regard, please be informed of the main issues and summary of MSC 101 as below.

For your information, the amendments to SOLAS, FSS Code, IGF Code and LSA code adopted at this session <u>will enter into force on 1 January 2024</u> in accordance with SOLAS 4 year cycle entry into force scheme, and in case of IBC Code, the amendment <u>will enter into force from 1st January 2021</u> instead of following SOLAS 4 year cycle scheme, because amendments to IBC Code were discussed under MEPC although the code is subordinated by SOLAS.

Moreover, please pay your attention that 2011 ESP Code consolidated version and amendments to IMSBC Code will enter into force from 1st January 2021.

In addition to the above, amendments to SPS Code will enter into force from 1st January 2020 separately.

1. Adoption of amendments to mandatory and non-mandatory instruments (Agenda 3)

1.1 Amendments to appendixes of SOLAS

Inserted footnote "Delete as appropriate" newly in Item 8.1 of Form C(Equipment Record of Cargo ship Safety Certificate), E(Equipment Record of Cargo ship Safety Equipment Certificate), and P(Equipment Record of Passenger ship Safety Certificate) "Rudder, Propeller, thrust, pitch and operational mode indicator" in order to enable it to delete some arrangements, which are not installed on the ship.



BRIEFING STATUS

✓ Flash

☐ Final.

No. IMO-0009-2019

Briefings of IMO Meeting are sequentially released by 2 steps as Flash - Final.

1.2 Amendments to FSS Code

The term "forward of", which are used in 2.2.3.2.1, 2.2.3.2.6 and 2.2.4.2.1 of FSS Code Chapter 15 was corrected as "downstream."

1.3 Major amendments to IGF Code
○ A requirement, which alleviates fuel oil loading conditions in cases where the tank insulation and tank location make the probability very small for the tank contents to be heated up due to an external fire, was added as 6.8.3 in Part A-1.
○ The existing requirement for fuel oil pipe to be protected by secondary enclosure in Part A-1 was divided into the requirements for gaseous fuel oil pipes and liquefied fuel pipes to be protected by secondary enclosure and they were added after 9.5.2.
○ A requirement was added as "exhaust system shall be equipped with explosion relief systems unless designed to accommodate the worst case overpressure due to ignited gas leaks or justified by the safety concept of the engine" in regulation 10.3 "Regulations for internal combustion engines of piston type" of Part A-1.
○ The requirement "The boundary between spaces containing fuel containment systems shall be either a cofferdam of at least 900 mm or A-60 class division" was deleted in 11.3.3 of Part A-1.
○ The following new regulation 11.3.3.1 was added after regulation 11.3.3 in Part A-1.
White tile is added to the control of the control o

"Notwithstanding 11.3.3, for ships constructed on or after 1st January 2024, for type C tanks, the fuel storage hold space may be considered as a cofferdam



BRIEFING STATUS

▼ Flash

☐ Final.

No. IMO-0009-2019

Briefings of IMO Meeting are sequentially released by 2 steps as Flash - Final.

provided the type C tank is not located directly above machinery spaces of category A or other rooms with high fire risk. When the fuel storage hold space is considered as a cofferdam, the minimum distance to the A-60 boundary from the outer shell of the type C tank or the boundary of the tank connection space, if any, shall be at least 900 mm."

1.4 Amendments to LSA Code

O Existing paragraph 4.4.8.1 was revised to that, existing 4.4.8.1 (which requires that thole pins, crutches or equivalent arrangements shall be provided for each oar provided) is not applied in case of a lifeboat equipped with two independent propulsion systems, where the arrangement consists of two separate engines, shaft lines, fuel tanks, piping systems and any other associated ancillaries.

O Existing paragraph 6.1.1.3 was revised as follows:

"6.1.1.3 On cargo ships equipped with a rescue boat which is not one of the ship's survival craft, having a mass not more than 700 kg in fully equipped condition, with engine, but without the crew, the launching appliance of the boat does not need to be fitted with stored mechanical power. Manual hoisting from the stowed position and turning out to the embarkation position shall be possible by one person. The force on the crank handle shall not exceed 160 N at the maximum crank radius of 350 mm. Means shall be provided for bringing the rescue boat against the ship's side and holding it alongside so that persons can be safely embarked."

1.5 Major amendments to IBC Code



BRIEFING STATUS

Tlash

☐ Final.

No. IMO-0009-2019

Briefings of IMO Meeting are sequentially released by 2 steps as *Flash - Final*.

1.6 Major amendments to IMSBC Code

Major amendment to IMSBC Code are summarized as follows;

- On Bauxite cargoes
 - Included new test procedure for determining TML(Transportable Moisture Limit) of Bauxite cargoes in Appendix 2
 - Included individual schedule of Bauxite cargoes as Group A newly
 - Existing individual schedule of Bauxite as Group C was revised
- On Seed Cake cargoes
 - New individual schedules for Seed Cake as Group C and Group B(MHB(SH)) addressing oxygen depletion issues
 - Amendments to existing individual schedule for Seed Cake UN 1386(a), UN 1386(b) and Seed Cake UN 2217



BR	IEFING	STATUS
√	Elach	

No. IMO-0009-2019

Wine at
rinal.

Briefings of IMO Meeting are sequentially released by 2 steps as Flash - Final.

On metal sulphide concentrate

- New individal schedule for metal sulphide concentrates, self-heating UN 3190 as group A and B cargo
- Ammonium Nitrate Based fertilizer (non-hazardous) remained classified as Group C with a footnote reference to the information contained in CCC.1/Circ.4 on carriage of Ammonium Nitrate Based fertilizer.

Others

- Amendment to the test method concerned with classifying materials producing flammable gases in wet condition

1.7 Amendments to ESP Code

ESP Code, which had been intended to be adopted as 2011 and 2019 ESP code individually, was adopted as one 2011 ESP Code consolidated version as an outcome of reviewing about administrative burden and other factors by Secretariat.

1.8 Major amendments to BCH Code

 The requirement that 'Hydrogen sulphide (H2S) detection equipment should 	l be
provided on board ships carrying bulk liquids prone to H2S formation' was add	ded
n Chapter 4 "Special requirements."	

The requirement that 'Where column o in the table of chapter 6 refers	to
paragraph 5.2.7, the cargo is subject to the prewash requirements in regulati	ion
13.7.1.4 of Annex II of MARPOL' was added in Chapter 5 "Operational requiremer	nts.′



BRIEFING STATUS

☐ Final.

No. IMO-0009-2019

Briefings of IMO Meeting are sequentially released by 2 steps as *Flash - Final*.

○ "15.15 4.24" and "16.2.7 5.2.7" were added in cross reference of "column o" about IBC/BCH Code requirements in Chapter 6 "Summary of Minimum requirements."

1.9 Amendments to SPS Code

MSC 100 adopted amendments to SPS Code, which would be effective from January 1st, 2020, in conjunction with amendment of SOLAS chapter 4 and appendixes (certificates) in last session.

Simultaneously, it was recognized that update of SPS Safety Certificate and equipment records of SPS Safety Certificate (i.e. addition of 'SART' and 'AIS-SART' to the list of radio equipment and so on) is needed.

Accordingly, MSC 101 adopted new amendment to SPS Code which reflected items in need of update on.

2. Maritime Autonomous Surface Ships (Agenda5)

The Committee reviewed the agenda documents concerning regulatory scoping exercise (hereinafter referred to as 'RSE') for the use of Maritime Autonomous Surface Ships (hereinafter referred to as 'MASS') and draft interim guidelines for MASS trials submitted by the Secretariat, member states and NGOs. The Committee established a working group (WG) to complete the draft interim guidelines for MASS trials and finalize the preparations for the Intersessional MSC Working Group held in September.

The Working Group shared the initial review of the RSE and determined the report format of first step RSE and Terms of Reference (TOR) for the Intersessional MSC Working Group. Based on the MSC101/5/5 (Interim guidelines for MASS trials) and



No. IMO-0009-2019

Briefings of IMO Meeting MSC 101 (5th Jun. ~ 14th Jun. 2019)

BRIEFING STATUS

▼ Flash

☐ Final.

Briefings of IMO Meeting are sequentially released by 2 steps as Flash - Final.

MSC101/5/6 (Comments on documents MSC 101/5/5 and MSC 101/INF.17) in relation to the interim guidelines for MASS trials, the main requirements were discussed and guidelines reflecting the discussion were finalized.

These guidelines were developed as a goal-based, high-level regulation in accordance with the development principles agreed at MSC 100/WG and have specific objectives such as 'Risk management', 'Compliance with mandatory instruments', 'Manning and qualifications of personnel involved in MASS trials', 'Human element and Human factors', 'Infrastructure for safe conduct of trials', 'Trial awareness', 'Communications and data exchange', 'Reporting requirements and information sharing', 'Scope and objective for each individual trial' and 'Cyber risk management'.

The Intersessional MSC Working Group for MASS RSE to be held in September 2019 will review the results of first step RSE and discuss the work scope of second step.

3. Goal Based Standards (GBS) (Agenda 6)

Regarding the current status of GBS verification audits, it was noted that the audit report on the rectification of non-conformities audit of Türk Loydu, the reverification audit of the DNV-GL rules and the maintenance audit of the remaining 11 IACS class societies will all be submitted to MSC 102.

It was informed that the new GISIS functionality for the pool of GBS auditors has been operational and ready to be used by Member States and international organizations for the nomination GBS auditors. The Committee decided to make GBS auditor information in the GISIS module available to all Member States and international organizations, except for certain private data.



No. IMO-0009-2019

Briefings of IMO Meeting MSC 101 (5th Jun. ~ 14th Jun. 2019)

BRIEFING STATUS

Flash

☐ Final.

Briefings of IMO Meeting are sequentially released by 2 steps as Flash - Final.

The Committee approved the revised Generic Guidelines for Developing IMO Goal-Based Standards (MSC.1/Circ.1394/Rev.2) that includes an example for the development of functional requirements, as new appendix 3, in order to address the uncertainties and misunderstandings on the application of the Generic guidelines for developing goal-based standards (MSC.1/Circ.1394/Rev.1).

4. Discussion on Safety Measures for Non-SOLAS Ships operating in Polar Water (Agenda 7)

MSC 101 agreed to include in the provisional agenda for NCSR 7 existing output on "Safety measures for non-SOLAS ships operating in polar waters. The Committee also agreed to instruct NCSR to consider consequences and feasibilities of applying chapters 9 and 11 of the Polar Code to non-SOLAS ships and how best to enhance the safety of non-SOLAS ships, including possible development of amendments to SOLAS and/or the Polar Code. Finally, the Committee decided to request NCSR 7 to take into account the outcome of the 2019 Torremolinos Conference on the Safety of Fishing Vessel.

5. Development of Further Measures To Enhance the Safety Of Ships Relating to the Use of Fuel Oil (Agenda 8)

MSC 101 convened a working group for dealing with safety issues which can be occurred by use of fuel oil that does not comply with minimum flashpoint requirements of SOLAS. During the session, the working group discussed about documentation and reporting non-compliance of flashpoint requirements, actions against oil fuel suppliers that have been found to deliver oil fuel that does not comply with minimum flashpoint requirements, guidelines for ships to address



No. IMO-0009-2019

Briefings of IMO Meeting MSC 101 (5th Jun. ~ 14th Jun. 2019)

BRIEFING STATUS

▼ Flash

☐ Final.

Briefings of IMO Meeting are sequentially released by 2 steps as Flash - Final.

situations where independent test results indicate that non-compliant oil fuel was delivered and development of GISIS module for reporting non-compliance of flashpoint requirements. In addition, the group prepared a draft MSC resolution on urgent guidance to enhance the safety of ships relating to the use of oil fuel.

Accordingly, MSC 101 adopted the above draft MSC resolution on "Recommended interim measures to enhance the safety of ships relating to the use of oil fuel" and agreed to develop a platform on GISIS for reporting of non-compliance of flashpoint requirements.

Finally, It was decided by MSC 101 that a correspondence group is established to consider the development of mandatory requirements regarding the reporting of confirmed cases where oil fuel suppliers have failed to meet the flashpoint requirements of the Organization including the development of mandatory requirements to ensure parties take action as appropriate against oil fuel suppliers in confirmed cases of deliveries of oil fuel that does not comply with the requirements specified in SOLAS regulation II-2/4.2.1, taking into account regulation 18.9.4 of MARPOL Annex VI and others.

6. Report of the Sub-committees (Agenda 9 ~ 14)

6.1 Approval of draft amendment to SOLAS II-1/3-8 relevant Circulars (Agenda 12, SDC 6)

Draft amendment to SOLAS II-1/3-8 was approved by MSC 101. It provides that, for ship equal to or more than 3,000 GT, design of mooring arrangements and the selection of appropriate mooring equipment and fittings for safe mooring shall be based on the instruction developed by the organization and, for ships less than 3,000 GT, it shall be based on the guidelines developed by the organization within flag administration.



BRIEFING STATUS

Flash

☐ Final.

No. IMO-0009-2019

Briefings of IMO Meeting are sequentially released by 2 steps as *Flash - Final*.

The above draft amendment requires mooring equipment including lines shall be maintained in appropriate condition for inspection and its original purpose also. In addition to the above, the draft Guidelines on the design of mooring arrangements and the selection of appropriate mooring equipment and fittings for safe mooring and the draft Guidelines for inspection and maintenance of mooring equipment including lines were approved with in principle a view to final approval in conjunction with the adoption of the draft amendments to SOLAS regulation II-1/3-8 at MSC 102. The Guidelines are expected to take effect on 1 January 2024 upon entry into force of the associated SOLAS amendments.

6.2 Relaxation of valve requirement used for foreward collision bulkhead of Passenger ships (Agenda 12, SDC 6)

New draft amendment on use of valve in collision bulkhead was approved during MSC 101. In the draft amendment to be entered into force in 2024, use of butterfly valve in foreward collision bulkhead, which will be allowed only to cargo ships by SOLAS amendments entering into force Jan. 1, 2020, was extended to passenger ships.

6.3 Ships carrying industrial Persons more than 12 (Agenda 12, SDC 6)

Application criteria of SOLAS Chapter 15(IP Code) was confirmed again and it was decided to reflect it on draft SOLAS amendment at SDC 7 (February, 2020). Application criteria is aggregate number of industrial personnel, special personnel and passengers, all member states agreed with the proposal to apply IP Code to the ship which carries more than total number of 12 industrial persons including special personnel and passengers.



BRIEFING STATUS

Flash

☐ Final.

No. IMO-0009-2019

Briefings of IMO Meeting are sequentially released by 2 steps as *Flash - Final*.

6.4 Approval of various unified interpretations (Agenda 12, SDC 6)

Following unified interpretations (UIs), developed or revised by SDC Sub-committee, were approved at this session;

- Revised Unified interpretations of the 2008 IS Code (MSC.1/Circ.1537) and the associated draft MSC circular, for dissemination as MSC.1/Circ.1537/Rev.1
- Revised Unified interpretations relating to the Protocol of 1988 relating to the International Convention on Load Lines, 1966 (MSC.1/Circ.1535) and the associated draft MSC circular, for dissemination as MSC.1/Circ.1535/Rev.1
- Revised Unified interpretations of SOLAS chapter II-1 (MSC.1/Circ.1539) and the associated draft MSC circular, for dissemination as MSC.1/Circ.1539/Rev.1
- Unified interpretation of SOLAS regulations II-1 regarding safe return to port requirements for flooding detection systems

6.5 Amendments to the Guidelines on alternative design and arrangements for SOLAS chapters II-1 and III (MSC.1/Circ.1212) (Agenda 14, SSE 6)

The amendments to the "Guidelines on alternative design and arrangements for SOLAS chapters II-1 and III" was approved as MSC.1/Circ.1212/Rev.1 at this session. The guidelines have served to outline the methodology for the engineering analysis required by SOLAS regulations II-1/55 and III/38 on alternative design and arrangements, applying to a specific engineering or life-saving system, design or arrangements for which the approval of an alternative design deviating from the prescriptive requirements of SOLAS chapters II-1 and III is sought. At this



BRIEFING STATUS

▼ Flash

☐ Final.

No. IMO-0009-2019

Briefings of IMO Meeting are sequentially released by 2 steps as *Flash - Final*.

amendments, the goals, functional requirements and expected performance criteria for SOLAS chapter III were added as Appendix 5 to the guidelines.

6.6 Interim guidelines on life-saving appliances and arrangements for ship operating in polar waters (Agenda 14, SSE 6)

As a consequential work related to the Polar Code, the interim guidelines on life-saving appliances and arrangements for ships operating in polar waters were approved at this session. This interim guidelines was developed to provide interim guidance outlining possible means of mitigating hazards in order to comply with section 8.3 of part I-A (life-saving appliances and arrangements) of the International Code for Ships Operating in Polar Waters (Polar Code).

6.7 Interim guidelines for minimizing the incidence and consequences of fires in ro-ro spaces and special category spaces of new and existing ro-ro passenger ships (Agenda 14, SSE 6)

As an output from the "Review SOLAS chapter II-2 and associated codes to minimize the incidence and consequences of fires on ro-ro spaces and special category spaces of new and existing ro-ro passenger ships" of last several years, the "Interim guidelines for minimizing the incidence and consequences of fires in ro-ro spaces and special category spaces of new and existing ro-ro passenger ships" were approved at this session.

6.8 Approval of various unified interpretations (Agenda 14, SSE 6)

Following unified interpretations (UIs), developed by SSE Sub-committee, were approved at this session;



BRIEFING STATUS

▼ Flash

Tinal

No. IMO-0009-2019

Briefings of IMO Meeting are sequentially released by 2 steps as *Flash - Final*.

- UIs of SOLAS chapter II-2 relating to the determination of fire integrity of divisions for the urea or sodium hydroxide solution tank spaces for selective catalytic reduction (SCR) systems, exhaust gas recirculation (EGR) systems or exhaust gas cleaning systems (EGCS)
- Uls of the IGC Code for paragraphs 11.3.6 (fire protection and extinction, water-spray system) and 11.4.8 (fire protection and extinction, Dry chemical powder fire-extinguishing systems)
- UIs of SOLAS chapter III relating to the 5-yearly thorough examinations, overhauls and operational tests of lifeboats, rescue boats and fast rescue boats, launching appliances and release gear, and UIs for the lifebuoys fitted with both a light and a lifeline as per MSC.1/Circular.1331
- Uls of SOLAS regulations II-1/28, II-1/29 and II-1/30 concerning the arrangement for steering capability and function on ships fitted with propulsions and steering systems other than traditional arrangements for a ship's directional control

7. Others (Work Programmes)

7.1 In-water performance of SOLAS lifejackets

The Committee considered documents proposing to review the LSA Code and resolution MSC.81(70) in respect of the in-water performance of SOLAS lifejackets; and agreed to include in the post-biennial agenda of SSE Sub-committee an output on "Development of amendments to the LSA Code and resolution MSC.81(70) to address the in-water performance of SOLAS lifejackets."

7.2 Performance standards for electronic inclinometers



BRIEFING STATUS

Flash

☐ Final.

No. IMO-0009-2019

Briefings of IMO Meeting are sequentially released by 2 steps as Flash - Final.

The Committee considered documents proposing the development of SOLAS amendments to make the Performance standards for electronic inclinometers (resolution MSC.363(92)) compulsory for container ships and bulk carriers; and agreed to include in the post-biennial agenda of NCSR Sub-Committee an output on "Development of SOLAS amendments for mandatory carriage of electronic inclinometers on container ships and bulk carriers."

7.3 Voyage data recorder and related performance standards

The Committee considered document proposing the development of amendments to SOLAS regulation V/20 on Voyage Data Recorders (VDRs) to require that all new VDRs and Simplified Voyage Data Recorder (S-VDRs) installations be float free and resolutions MSC.333(90) on Adoption of revised performance standards for shipborne voyage data recorders (VDRS), and MSC.163(78), on Performance standards for shipborne simplified voyage data recorders (S-VDRs) to include the recording of all communications between control stations and both sides of all communications with the bridge, and agreed to include in the post-biennial agenda of NCSR Sub-committee.

General Manager of
Convention & Legislation Service Team

P.I.C:

Heo Kang-Yi / Senior surveyor Convention & Legislation Service Team

Tel: +82 70 8799 8322 Fax: +82 70 8799 8339

E-mail: convention@krs.co.kr

Disclaimer

Although all possible efforts have been made to ensure correctness and completeness of the contents contained in this information service, the Korean Register of Shipping is not responsible for any errors or omissions made herein, nor held liable for any actions taken by any party as a result of information retrieved from this information service